

ACA LEAKAGE TESTER



TABLE OF CONTENTS

1. FEATURES.....	1
2. SPECIFICATIONS.....	1
3. FRONT PANEL DESCRIPTION.....	2
3-1 Current Sense Jaw.....	2
3-2 Off/On/Hold Switch.....	2
3-3 200mA/20A/200A Switch.....	2
3-4 Display.....	2
3-5 Battery Compartment.....	2
4. PRECAUTIONS & PREPARATIONS FOR MEASUREMENT.....	3
5. MEASURING PROCEDURE.....	3
5-1 AC mA Leakage Current Measurement.....	3
5-2 20A, 200A AC Current Measurement.....	3
5-3 Data Hold.....	4
6. REPLACEMENT OF BATTERY.....	4

1. FEATURES


- * High precision AC mA measurement, it is useful for AC mA leakage current measurement.
- * Measure AC mA on the inductive conductor.
- * Miniature type, easy to carry out & operation.
- * High precision for low ACA leakage current measurement.
- * Built-in DATA HOLD function.
- * Crystal time base, high quality.
- * LCD display allows clear readout-out even at high ambient light level.
- * LSI circuit provides high reliability and durability.
- * Overload protection circuit is provided for all range.
- * Design to meet IEC 1010 safety requirement.
- * Compact, light weight and excellent operation.

2. SPECIFICATIONS

Display	13 mm (0.5") LCD, 3 1/2 digits. Max. indication 1999.
Measurement & Resolution	200 AC mA x 0.1 mA 20 ACA x 0.01 A 200 ACA x 0.1 A
Data Hold	Available to hold the measuring values on the display.
Accuracy (23 5 ㉞)	(1.2 % + 5 d) <i>* Specification be tested on sine wave 50, 60 Hz.</i>
Time Base	Quartz crystal, 32768 Hz.
Overload Circuit Protection	300 ACA max. (within 1 minute for 20A, 200A range).
Zero adjustment	Automatic adjustment.
Over input	Display shows '1'.
Sampling Time	Approx. 0.4 second.

Operating Temp.	0 蛭 to 50 蛭 (32 蚌 to 122 蚌).	
Operating Humidity	Less than 80% RH.	
Battery	006P DC 9V battery.	
Power Consumption	Approx. DC 1.2 mA.	
Weight	200 g/0.44 LB (including battery).	
Dimension	HWD 180 x 47 x 35 mm. 7.1 x 1.9 x 1.4 inch.	
Conductor Size	19 mm Dia.	
Accessories	Operation manual.....	1 PC.
Included	Carrying case.....	1 PC.

3. FRONT PANEL DESCRIPTION



Fig, 1

- | | |
|------------------------------|-------------------------|
| 3-1 Current Sense Jaw | 3-4 Display |
| 3-2 Off/On/Hold Switch | 3-5 Battery Compartment |
| 3-3 200 mA/20 A/200 A Switch | |

4. PRECAUTIONS & PREPARATIONS FOR MEASUREMENT

- 1) Ensure that the DC 9V battery is connected correctly to its snap terminal and placed in the battery compartment.
- 2) When apply the " DATA HOLD " function, slide the " Off/On/Hold Switch " (3-2, Fig. 1) to the " Hold " position. Otherwise it is necessary to slide the " Off/On/Hold switch " to " On " position always.
- 3) Do not measure current over the maximum limit.
- 4) Always select the " Power On/Off/Hold " switch to the " Off " position when the instrument does not use. Remove the battery if the instrument is not to be used for a long period of time.

5. MEASURING PROCEDURE

5-1 AC mA Leakage Current Measurement

- 1) Select the " Power On/Off/Hold switch " (3-2, Fig.1) to the " On " position.
- 2) Select the " 200mA/20A/200A Switch " (3-3, Fig. 1) to the " 200 mA " position.
- 3) Press the trigger to open the "Current Sense Jaw" (3-1, Fig. 1). & clamp on the measured conductor only.
- 4) Read AC mA leakage current on the display directly.

5-2 20A, 200A AC Current Measurement

- 1) Select the " Power On/Off/Hold switch " (3-2, Fig. 1) to the " On " position.
- 2) Determine the highest anticipated current (200 A, 20 A) on the " 20 A/200 A Switch " (3-3, Fig. 1) and select to the corresponding position.
- 3) Press the trigger to open the " Current Sense Jaw " (3-1, Fig. 1) & clamp on the measured conductor only.
- 4) Read ACA values on the display directly.

5-3 Data Hold

When make any measurement, if select the " On/Off/Hold Switch " (3-5, Fig. 1) to the " Hold " position will keep the data on the display. It will release the data hold function if select the " On/Off/Hold Switch " to the " On " position again.

6. REPLACEMENT OF BATTERY

- 1) When the left corner of LCD display show "LOBAT", it indicate a normal battery output that less than 6.5 V - 7.5 V and it is necessary to replace the battery. However in-spec measurement may still be made for several hours after low battery indicator appears before the instrument become inaccurate.
- 2) Open the " Battery Cover " (3-5. Fig 1), use the " - " type screw driver or small coin to open the battery cover away from the instrument and remove the battery.
- 3) Replace with 9V battery and reinstate the cover.