

100 Kg x 0.05 Kg, Kg/LB/Newton, RS232

FORCE GAUGE

Model : FG-5100




TABLE OF CONTENTS

| | |
|--|---|
| 1 FEATURES..... | 1 |
| 2 SPECIFICATIONS..... | 1 |
| 3 FRONT PANEL DESCRIPTIONS | 4 |
| 3-1 Sensor socket..... | 4 |
| 3-2 LCD Display..... | 4 |
| 3-3 Fast Indicator..... | 4 |
| 3-4 FAST/SLOW Button..... | 4 |
| 3-5 LCD Reverse Display Button..... | 4 |
| 3-6 Zero Button..... | 4 |
| 3-7 Kg/LB/Newton Unit Switch..... | 4 |
| 3-8 Power Off/On/Peak Hold..... | 4 |
| 3-9 Mounting Holes/fixing Screws..... | 4 |
| 3-10 Battery Cover/Compartment..... | 4 |
| 3-11 DC 9V power adapter input socket..... | 4 |
| 3-12 Sensor hook..... | 4 |
| 3-13 Sensor (force sensor)..... | 4 |
| 3-14 Sensor plug..... | 4 |
| 3-15 RS-232 output terminal..... | 4 |
| 3-16 LCD Back Light Button | |
| 4 MEASURING PROCEDURE | 5 |
| 4-1 Preparations For Measurement | 5 |
| 4-2 Normal Measurement | 6 |
| 4-3 Peak Hold Measurement | 6 |
| 4-4 LCD Back light On/Off | |
| 5 BATTERY REPLACEMENT | 7 |
| 6 RS232 PC SERIAL INTERFACE..... | 7 |
| 7 APPLICATIONS..... | 9 |

1. FEATURES

- * Large LCD display with back light.
- * Tension & compression capability .
- * 100 Kg, wide capacity, high resolution, high accuracy, high repeatability.
- * 3 kind display unit, Kg/LB/Newton.
- * Seperate sensor.
- * Peak hold (Max. load) can be held in display during make tension or compression measurement.
- * Zero button can operate both for normal measuring & the " peak hold " operation.
- * Full capacity zero (tare) control capability.
- * Fast/Slow response time push button.
- * Positive or reverse display direction select.
- * Over load protection.
- * Hand held & stand mounting available.
- * Low power consumption gives long battery life.
- * Build in low battery indicator.
- * Microprocessor circuit & exclusive load cell transducer.
- * RS-232 computer interface .
- * Power supply built-in DC 9V adapter input socket.

2. SPECIFICATIONS

| | |
|---------|---|
| Display | LCD (Liquid crystal display). 5 digits, 16 mm (0.63") digit size. Back light. |
|---------|---|

| | |
|-----------------------|--|
| Display Direction | Positive or Reverse direction, select by the push button on the front panel. |
| Function | Tension & Compression (Push & Pull). Normal force, Peak hold (Max. load). |
| Peak hold | Will freeze the display value of the Peak load (Max. load). |
| Zero | Zero button can be operated both for "normal force" or "peak hold" operation |
| Unit select | Kg/LB/Newton |
| Measure Capacity | 100 Kg/220 LB/980 Newton. |
| Resolution | 0.05 Kg/0.05 LB/0.2 Newton. |
| Min. Display | 0.15 Kg/0.35 LB/1.4 Newton. |
| Accuracy | \pm (0.5 % + 2 digits), within $23 \pm 5^{\circ}\text{C}$. <i>* Under the test weight on 100 Kg & 10 Kg.</i> |
| Update time | Fast Approx. 0.2 second. Slow Approx. 0.6 second. |
| Over range Indicator | Display show " - - - - " when in over range status. |
| Data output | RS-232 serial computer interface. |
| Overload Capacity | Max. 150 kg. |
| Full Scale Deflection | Less than 1 mm. |
| Zero/tare Control | Max. full capacity. |
| Circuit | Exclusive microprocessor LSI-circuit. |
| Sensor type | S type load cell. |
| Power Supply | 6 x 1.5 V AA (UM-3) size battery or DC 9V adapter (not included). |

| | |
|-----------------------|--|
| Power Consumption | Approx. DC 28 mA |
| Operating Temperature | 0°C to 50°C (32°F to 122°F). |
| Operating Humidity | Less than 80% RH. |
| Dimension | <i>Main instrument :</i> 215 x 90 x 45 mm (8.5 x 3.5 x 1.8 inch). |
| | <i>Sensors with two hooks :</i> 130 x 51 x 18 mm (4.7 x 2.0 x 0.7 inch). |
| | <i>Cable length :</i> 2 meters. |
| Weight | <i>Main instrument :</i> 450 g (0.99 LB). |
| | <i>Sensors :</i> 380 g (0.84 LB). |
| Mounting Holes | Main instrument with mounting holes are provided on the back case, easy stand mounting. |
| Accessories Included | Operating manual1 PC. 100 Kg sensor with 2 hooks and 2 meter cable.....1 PC. Hard carrying case 1 PC. |
| Optional Accessories | * RS232 cable, Model : UPCB-02. * Software for data logging & data recorder. Model : SW-U801-WIN. |

3. FRONT PANEL DESCRIPTION




Fig. 1

- | | |
|---|---------------------------------------|
| 3-1 Sensor socket | 3-9 Mounting Holes/fixing Screws |
| 3-2 LCD Display | 3-10 Battery Cover/Compartment |
| 3-3 Fast Indicator | 3-11 DC 9V power adapter input socket |
| 3-4 FAST/SLOW Button | 3-12 Sensor Hook |
| 3-5 LCD Reverse Display Button | 3-13 Sensor (force sensor) |
| 3-6 Zero Button | 3-14 Sensor plug |
| 3-7 Kg/LB/Newton Unit Switch | 3-15 RS-232 output terminal |
| 3-8 Power Off/On/Peak Hold 0 = Off, 1 = On | 3-16 LCD Back Light Button |

4. MEASURING PROCEDURE

4-1 Measuring Consideration

- 1) The Tension & Compression measuring function is executed automatically.
When make the compression measurement, the display will show the " - " mark automatically.
- 2) When make the measurement, the " Sensor " (3-13, Fig. 1) should be on a line with measuring object.
- 3) Rotate the sensor's body is prohibited. Some certain angles between " Sensor " (3-13, Fig.1) & measuring object are not allowed.

4-2 Normal Measurement

- 1) Connect the " Sensor Plug " (3-14) to the " Sensor socket " (3-1, Fig.1).
Slide the " Power Off/On/Peak Hold Switch " (3-8, Fig. 1) to the " On " position.
- 2) Determine display unit of Kg, LB or Newton by selecting " Kg/LB/Newton Unit Switch " (3-7, Fig. 1).
- 3) Connect " Sensor " (3-13, Fig. 1) with the " Measuring Object " via the " Sensor hook " (3-12, Fig. 1) in straight line.
- 4) " Zero Adjust " by pushing " Zero Button " (3-6, Fig. 1) before every measurement.
- 5) Start measurement by giving force (push or pull), then the LCD will display the Average reading value.

Note :

** During the measurement, if intend to change the display direction, just push the " Reverse Button " (3-5, Fig. 1) once.*

- * There are two kind sampling time of display, FAST and SLOW. Push the " FAST/SLOW Button " once (3-4, Fig. 1), if the upper left corner of LCD shows " FAST " (Fast Indicator, 3-3, Fig. 1), then the display reading is under the operation of fast sampling time.
- * If the upper left corner of LCD not show the " Fast Indicator " (3-3, Fig. 1), the display reading is under the slow sampling time.
- * Over range display of tension function, LCD will show " ----- "
- * Over range display of compression function, LCD will show " ----- "

4-3 Peak Hold Measurement

The meter can measure the peak value of force both of tension & compression operation. The operation procedures of Peak Hold Measurement are same as above " 4-2 Normal Measurement " but should slide the " Power Off/On/Peak Hold Switch " (3-8, Fig. 1) to the " PEAK H. " position.

Slide the " Power Off/On/Peak Hold Switch " (3-8, Fig. 1) to the " On " position will cancel the peak hold function.

4-4 LCD Back Light On/Off

During the measurement, press the " LCD Back Light Button " (3-16, Fig. 1) momentarily, will turn on the LCD Back Light structure approx. 15 seconds automatically then off.

5. BATTERY REPLACEMENT


- 1) When the LCD shows " Lo ", it is necessary to replace the batteries. However, in-spec. measurement may still be made for several hours after low battery indicator appears before the instrument become inaccurate.
- 2) Take out the battery cover (3-10, Fig. 1) away from the instrument and remove the batteries.
- 3) Install the batteries ((6 x 1.5 V AA, UM-3) correctly into the battery case.

6. RS232 PC SERIAL INTERFACE

The instrument features an RS232 output via 3.5 mm Terminal (3-15, Fig. 1).

The connector output is a 16 digit data stream which can be utilized to the user's specific application.

An RS232 lead with the following connection will be required to link the instrument with the PC serial input.



The 16 digit data stream will be displayed in the following format :

D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0

Each digit indicate the following status :

| | |
|-----------|---|
| D0 | End Word |
| D1 & D8 | Display reading, D1 = LSD, D8 = MSD <i>For example :</i> <i>If the display reading is 1234, then D8 to D1 is : 1234</i> |
| D9 | Decimal Point(DP), position from right to the left 0 = No DP, 1= 1 DP, 2 = 2 DP, 3 = 3 DP |
| D10 | Polarity 0 = Positive 1 = Negative |
| D11 & D12 | Anunciator for Display |
| | g = 57 Newton = 59 oz =58 |
| | Kg = 55 LB = 56 |
| D13 | 1 |
| D14 | 4 |
| D15 | Start Word |

RS232 setting

| | |
|--------------|-------------|
| Baud rate | 9600 |
| Parity | No parity |
| Data bit no. | 8 Data bits |
| Stop bit | 1 Stop bit |

7. APPLICATIONS

7-1 Electronics

- * Test strength of solder points and spot welds on circuit boards.
- * Test wire wraps on clip connection.
- * Test pull strength of modified wire wrap connection on posts.
- * Test spring clip insertion and withdrawal forces.
- * Pull test welds in micro-electronic devices.
- * Measure torque, timing belt tension, sliding friction, etc., on computer peripheral equipment.
- * Test P.C. board insertion force.
- * Test insertion and withdrawal forces of various circuit components such as transistors and integrated circuits.
- * Test actuating force of snap action switches.

7-2 Business Equipment

- * Measure force required to perforate cards.
- * Measure load on slitter knives.
- * Measure actuating requirements of typewriter.
- * Test clutch release force.
- * Measure torque, timing belt tension (by deflection), sliding friction, etc., on computer peripheral equipment.
- * Test adhesion strength of labels and stickers.
- * Test load on paper thickness gages.
- * Measure tension of pencils.
- * Test actuating requirements on push buttons and flip switches.

7-3 Chemical & Plastics

- * Test film bond strengths.
- * Tensile test rubber, fibers and filaments.
- * Measure firmness of polyurethane foam.
- * Test crush strength of pills (medicine)
- * Test peel strength of adhesives.
- * measure compression of ceramic compounds.
- * Test vacuum take-down pressure on process machines.

7-4 Machinery & Manufacturing

- * Test load on wire feel
- * Test force to open cabinet doors.
- * Test sprocket chain tension.
- * Test pull-out force of drive shaft.
- * Rate testing of springs in systems.
- * Calibrate a cantilever beam-type Apparatus to obtain a force/deflection relationship.

7-5 Automotive

- * Measure force of seat belt retractors.
- * Measure arm pressure of windshield wipers.
- * Measure flip force in mechanical snap action switches.
- * Test effort to operate hand tool.
- * Test forces required to move linkages and tension cables.
- * Measure force of odometer pull.
- * Test peel strength of vinyl insert bonded to body side moldings
- * Evaluate physical efforts (door, lock, hood, glove compartment, brake pedal, etc.).

7-6 Other Industries

- * Measure pedal depression force in aircraft.
- * Test hardness of gypsum wallboard.
- * Test keyboard and pedal contact force of organs and pianos.
- * Test force to remove cover tops of aerosol cans.
- * Measure trigger pulling forces on firearms, hand tools etc.
- * Test firmness of sausages in casings.
- * Test integrity of seals on blister packages and plastic bags.
- * Test pressure of surgical instruments (forceps, scissors).
- * Test fruit removal force and fruit firmness.
- * Measure force on spindles of photographic equipment