

# HUMIDITY/TEMP. CONTROLLER/MONITOR

Model : PHT-3109



Your purchase of this HUMIDITY/TEMP. CONTROLLER, MONITOR marks a step forward for you into the field of precision measurement. Although this METER is a complex and delicate instrument, its durable structure developed. Please read the following instructions carefully and always keep this manual within easy reach.

## OPERATION MANUAL

## Caution Symbol



**Caution :**

- \* Risk of electric shock !



**Caution :**

- \* Do not use fingers or any tool to touch the Wire Terminals.
- \* Do not apply the relay contact load current > 0.5 Amp.
- \* The instrument contains no user serviceable parts and should not be opened by the user.
- \* Repair or after service should be done by a qualified technician only.
- \* Power supply should apply the correct ACV power voltage
- \* Cleaning - Only use the dry cloth to clean the plastic case !



- \* **Equipment protected throughout by Double Insulation or Reinforced Insulation.**

## Environmental Condition

- \* Comply with EN61010.  
Transient overvoltage at Mains Supply 2500V.
- \* Pollution Degree 2.
- \* Altitude up to 2000 meters.
- \* Indoor use.
- \* Relative humidity 80% max.

## TABLE OF CONTENTS

1. FEATURES.....	1
2. SPECIFICATIONS.....	1
2-1 General Specifications.....	1
2-2 Electrical Specifications.....	3
3. FRONT PANEL DESCRIPTION.....	4
3-1 Display.....	4
3-2 PV ( process value ) indicator.....	4
3-3 SV ( set value ) indicator.....	4
3-4 Set Button.....	4
3-5 ▼ Button.....	4
3-6 ▲ Button.....	4
3-7 RH/Temp Button.....	4
3-8 %RH control relay indicator.....	4
3-9 Temp. control relay indicator.....	4
3-10 %RH ( humidity ) indicator.....	4
3-11 Temp. indicator.....	4
3-12 Wire terminals .....	4
3-13 RS232 terminal.....	4
3-14 Input socket .....	4
3-15 Case holder .....	4
3-16 Probe plug.....	4
3-17 Probe head ( Humidity & Temperature ).....	4
3-18 Probe handle.....	4
3-19 Probe fix holder.....	4
4. MEASURING PROCEDURE.....	5
4-1 Terminal connection.....	5
4-2 Humidity/Temp. measurement.....	5
4-3 1st layer setting procedures.....	6
4-4 2nd layer setting procedures.....	8
5. RS232 PC SERIAL INTERFACE.....	12
6. SYSTEM RESET.....	14
7. THE ADDRESS OF AFTER SERVICE CENTER.....	15


## 1. FEATURES

- \* Professional Humidity measurement monitor and controller.
- \* Build in humidity control relay and the Temp. control relay.
- \* Relay will be make action ( On/Off ) when the reading value reach high limit or low limit value.
- \* Offset value setting.
- \* Hysteresis value setting for high and low alarm.
- \* °C, °F temp. unit setting with default.
- \* High precision humidity sensor with fast response time and high accuracy.
- \* Large red LED display, high brightness and easy to read.
- \* RS232 computer interface, send out the humidity and the temperature data at the same time.
- \* Optional data acquisition software.
- \* Optional GSM controller.
- \* Microprocessor circuit ensures high accuracy and provides special functions and features.
- \* Standard 96 X 48 mm DIN case.

## 2. SPECIFICATIONS

### *2-1 General Specifications*

Display	4 digits red LED, digit size : 14 mm.	
Unit	Temp.	°C, °F
	Humidity	%RH
Circuit	Custom chip of microprocessor LSI circuit.	
Sensor Structure	Humidity	Semiconductor
	Temperature	Semiconductor

Sampling Time	Approx. 1 second.	
Relay outputs	Number	2 relays
	Function	<i>Relay 1 :</i> Humidity control relay. <i>Relay 2 :</i> Temperature control relay.
	Max load 	0.5 ACA/250 ACV 0.5 DCA/24 DCV <b><i>* Do not apply the relay contact load current &gt; 0.5 A, other wise the relay may be damaged permanently without warranty.</i></b>
Setting value	High limit value setting. Low limit value setting. Hysteresis value setting. Offset value setting. <b><i>* Setting for Humidity and Temp.</i></b>	
External Power Supply	DC 12 V, 50 mA max.	
Data Output	RS 232 PC serial interface.	
Operating Temperature	0 to 50 °C. <b><i>* Meter</i></b>	
Operating Humidity	Less than 80% R.H. <b><i>* Meter</i></b>	
Power Supply	90 to 260 ACV, 50/60 Hz.	
Power Consumption	Approx. 4.7 VA/AC 110V. Approx. 5.3 VA/AC 220V.	
Weight	384 g/ 0.84 LB. <b><i>* Including probe.</i></b>	
Dimension	DIN size : 96 x 48 mm. Depth : 110 mm.	
Accessories Included	Instruction manual.....1 PC Humidity/Temp. probe..... 1 PC Case holder with screw..... 2 PCs Probe fix holder..... 1 PC	

Optional Accessories	* Data Acquisition software, SW-U801-WIN.
	* RS232 cable, UPCB-02.
	* GSM controller, GSM-889.
	* Interface cable ( cable between meter to GSM-889 ), GMCB-89.

## ***2-2 Electrical Specifications (23± 5 °C)***

### ***Humidity***

Range	10 % to 95 % R.H.
Resolution	0.1 % R.H.
Accuracy	$\geq 70\% \text{ RH}$ $\pm (3\% \text{ reading} + 1\% \text{ RH}).$ $< 70\% \text{ RH} - 3\% \text{ RH}.$ $\pm 3\% \text{ RH}.$

### ***Temperature***

Measuring Range	0 °C to 50 °C/32 °F to 122 °F
Resolution	0.1 °C/0.1 °F
Accuracy	$\pm 0.8 \text{ °C}/1.5 \text{ °F}$

\* The above specifications is for the probe only.

\* Above specification tests under the environment RF Field Strength less than 3 V/M & frequency less than 30 MHz only.

### 3. FRONT PANEL DESCRIPTION





Fig. 1

- 3-1 Display
- 3-2 PV ( process value ) indicator
- 3-3 SV ( set value ) indicator
- 3-4 Set Button
- 3-5 ▼ Button
- 3-6 ▲ Button
- 3-7 RH/Temp Button
- 3-8 %RH control relay indicator
- 3-9 Temp. control relay indicator
- 3-10 %RH ( humidity ) indicator
- 3-11 Temp. indicator
- 3-12 Wire terminals
- 3-13 RS232 terminal
- 3-14 Input socket
- 3-15 Case holder
- 3-16 Probe plug
- 3-17 Probe head ( Humidity & Temperature )
- 3-18 Probe handle
- 3-19 Probe fix holder


## 4. MEASURING PROCEDURE



Terminal layout Fig. 2

### 4-1 Terminal connection

- 1) Input the ACV power ( 90 to 260 ACV ) to T1, T2.



**Do not input the over voltage to the AC input terminals.**

- 2) Connect the " Humidity Control Relay " output from T3, T4.  
Connect the " Temp. Control Relay " output from T5, T6.

### 4-2 Humidity/Temp. measurement

- 1) Connect the " Probe plug " ( 3-16, Fig. 1 ) to " Input socket " ( 3-14, Fig. 1 ).
- 2) Power on the meter, the " Display " ( 3-1, Fig. 1 ) will show the humidity value, in the same time the " %RH indicator " ( 3-10, Fig. 1 ) will light.



- 3) Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once, the " Temp. indicator " ( 3-11, Fig. 1 ) will light, the " Display " ( 3-1, Fig. 1 ) will show the Temp. value.

*\* Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once again, the " Display " will return the " Humidity value ", in the same time the " %RH indicator " ( 3-10, Fig. 1 ) will light again.*

#### ***4-3 1st layer setting procedures***

<b>LoLt</b>	<b>Low Limit</b>
<b>HiLt</b>	<b>High Limit</b>

#### ***Low Limit Value Setting***

- 1) Press the " Set Button " ( 3-4, Fig. 1 ) once, the " Display " will show " LoLt ", now the meter is ready for the Humidity " Low Limit " value setting.

Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once, the " Temp indicator " ( 3-11, Fig. 1 ) will light, now the meter is ready for the Temperature " Low Limit " value setting.

#### ***Remark :***

- \* Under " Display " show " LoLt ", if " % RH indicator " ( 3-10, Fig. 1 ) is lit, meter is ready for " Humidity Low Limit " setting.*
- \* Under " Display " show " LoLt ", if " Temp. indicator " ( 3-11, Fig. 1 ) is lit, meter is ready for " Temperature Low Limit " valuesetting.*
- \* The function of " Low Limit value " setting, refer to page 10, Fig. 2.*

- 2) Use the " ▼ Button " ( 3-5, Fig. 1 ) and the " ▲ Button " ( 3-6, Fig. 1 ) to adjust the desiring " Low Limit " value.

*\* When adjust the value, the " SV indicator " ( 3-3, Fig. 1 ) will light.*

### **High Limit Value Setting**

- 1) After set the " Low Limit " value, press the " Set Button " ( 3-4, Fig. 1 ) twice, the " Display " will show " HILt ", now the meter is ready for the humidity " High Limit " value setting.

Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once, the " Temp indicator " ( 3-11, Fig. 1 ) will light, now the meter is ready for the Temperature " High Limit " value setting.

#### **Remark :**

*\* Under " Display " show " HILt ", if " % RH indicator " ( 3-10, Fig. 1 ) is lit , meter is ready for " Humidity High Limit value " setting.*

*\* Under " Display " show " HILt ", if " Temp. indicator " ( 3-11, Fig. 1 ) is lit, it meter is ready for " Temperature High Limit value " setting.*

*\* The function of " High Limit value " setting, refer to page 10, Fig. 2.*

- 2) Use the " ▼ Button " ( 3-5, Fig. 1 ) and the " ▲ Button " ( 3-6, Fig. 1 ) to adjust the desiring " High Limit " value.

*\* When adjust the value, the " SV indicator " ( 3-3, Fig. 1 ) will light.*

After adjust the " High Limit " value, press the " Set Button " ( 3-4, Fig. 1 ) twice, " Display " will return to the normal measuring screen.

#### ***4-4 2nd layer setting procedures***

<b>tPty</b>	<b>Temp. unit setting</b>
<b>HySt</b>	<b>Hysteresis setting</b>
<b>oFSt</b>	<b>Offset setting</b>

#### ***Temperature unit setting***

- 1) Press the " Set Button " ( 3-4, Fig. 1 ) continuously at least two seconds, the " Display " will show " tPty ", now the meter is ready for the Temperature unit ( °C, °F ) setting.
- 2) Use the " ▼ Button " ( 3-5, Fig. 1 ) and the " ▲ Button " ( 3-6, Fig. 1 ) to adjust the desiring temperature unit to " C " or " F ".

*\* When adjust the Temp. unit, the " SV indicator " ( 3-3, Fig. 1 ) will light.*

### ***Hysteresis value setting***

- 1) After select the temperature unit ( °C, °F ), press the " Set Button " ( 3-4, Fig. 1 ) twice, the " Display " will show " HySt ", now the meter is ready for the the Hysteresis value setting.
- 2) Use the " ▼ Button " ( 3-5, Fig. 1 ) and the " ▲ Button " ( 3-6, Fig. 1 ) to adjust the desiring Hysteresis setting value.

*\* When adjust the Hysteresis value, the " SV indicator " ( 3-3, Fig. 1 ) will light.*

Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once, the " Temp indicator " ( 3-11, Fig. 1 ) will light, now the meter is ready for the Temperature " Hysteresis " value setting.

#### ***Remark :***

- \* Under " Display " show " HySt ", if " % RH indicator " ( 3-10, Fig. 1 ) is lit, meter is ready for " Humidity Hysteresis value " setting.*
- \* Under " Display " show " HySt ", if " Temp. indicator " ( 3-11, Fig. 1 ) is lit, meter is ready for " Hysteresis value " setting.*
- \* The function of " Hysteresis value " setting, refer to page 10, Fig. 2.*




Fig. 2

High limit value : 100

Low limit value : 20

Hysteresis value : 5

- \* **The control relay will On when measuring value up to 100. The control relay will Off again when measuring value down to 95.**
- \* **The control relay will On when measuring value down to 20. The control relay will Off when measuring value up to 25.**

### Offset value setting

- 1) After finish the Hysteresis setting, press the " Set Button " ( 3-4, Fig. 1 ) twice, the " Display " will show " oFSt ", now the meter is ready for the the offset value setting.
- 2) Use the " ▼ Button " ( 3-5, Fig. 1 ) and the " ▲ Button " ( 3-6, Fig. 1 ) to adjust the desiring offset value.
  - \* *When adjust the Offset value, the " SV indicator " ( 3-3, Fig. 1 ) will light.*

Press the " RH/Temp Button " ( 3-7, Fig. 1 ) once, the " Temp indicator " ( 3-11, Fig. 1 ) will light, now the meter is ready for the Temperature " Offset " value setting.

**Remark :**

- \* Under " Display " show " oFSt ", if " % RH indicator " ( 3-10, Fig. 1 ) is lit, meter is ready for " Humidity Offset value " setting.**
- \* Under " Display " show " oFSt ", if " Temp. indicator " ( 3-11, Fig. 1 ) is lit, meter is ready for " Temperature Offset value " setting.**
- \* For example of " Offset value setting " :**

The reading value is 102.

The offset value is 5.


***The new display value will be 107 ( 102 + 5 ).***

## 5. RS232 PC SERIAL INTERFACE

The instrument has RS232 PC serial interface via a 3.5 mm terminal ( 3-13, Fig. 1 ).

The data output is a 16 digit stream which can be utilized for user's specific application.

A RS232 lead with the following connection will be required to link the instrument with the PC serial port.



The 16 digits data stream will be displayed in the following format :

D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0

**Each digit indicates the following status :**

D15	Start Word
D14	4
D13	When send the upper display data = 1 When send the lower display data = 2
D12 & D11	Annunciator for Display
	°C = 01      °F = 02      m/S = 08
	km/h = 10    mph = 12      knot = 09
	FPM = 11      %RH = 04      dB = 17
	LUX = 15      Ft-cd = 16
D10	Polarity 0 = Positive    1 = Negative
D9	Decimal Point(DP), position from right to the left 0 = No DP, 1= 1 DP, 2 = 2 DP, 3 = 3 DP
D8 to D1	Display reading, D8 = MSD, D1 = LSD. For example : If the display reading is 1234, then D8 to D1 is : 00001234
D0	End Word

### **RS232 setting**

Baud rate	9600
Parity	No parity
Data bit no.	8 Data bits
Stop bit	1 Stop bit



## 6. SYSTEM RESET

Power on the meter, use the two fingers to press " Set Button " ( 3-4, Fig. 1 ) and " RH/Temp. Button " ( 3-7, Fig. 1 ) continuously more than 5 seconds until the Display show the text " rSt ", release the buttons. After " rSt " text flashing 2 times will return to the normal screen. The meter system will be reset, all the calibration data will be cleared, the meter's internal function will return the default value.

## **7. THE ADDRESS OF AFTER SERVICE CENTER**

