


*200  $\mu$ S/2 mS/20 mS/200 mS, TDS ( PPM )*

*Real time data logger, 16000 Data logger no., RS232*

# **CONDUCTIVITY METER**

**Model : YK-2005CD**



# TABLE OF CONTENTS

|                                                     |    |
|-----------------------------------------------------|----|
| 1. FEATURES.....                                    | 1  |
| 2. SPECIFICATIONS.....                              | 2  |
| 2-1 General Specifications.....                     | 2  |
| 2-2 Electrical Specifications.....                  | 4  |
| 3. FRONT PANEL DESCRIPTION.....                     | 5  |
| 4. GENERAL MEASURING PROCEDURE.....                 | 7  |
| 4-1 Conductivity ( uS, mS ) measurement.....        | 8  |
| 4-2 TDS ( PPM ) measurement.....                    | 9  |
| 4-3 Data Hold.....                                  | 10 |
| 4-4 Data Record (Max., Min. reading).....           | 10 |
| 4-5 Data Logger.....                                | 11 |
| 5. ADVANCED ADJUSTMENT PROCEDURE.....               | 12 |
| 5-1 Check Memory Space.....                         | 14 |
| 5-2 Clear Memory.....                               | 14 |
| 5-3 Date/Time Setting.....                          | 14 |
| 5-4 Sample Time Setting.....                        | 15 |
| 5-5 Auto Power Off Default Setting.....             | 15 |
| 5-6 Temp. Unit Default Setting.....                 | 15 |
| 5-7 Temp. Compensation Factor Default Setting.....  | 16 |
| 5-8 CD ( uS, mS ), TDS ( PPM ) Default Setting..... | 16 |
| 5-9 Escape from the SETTING function.....           | 16 |
| 6. HOW TO SEND THE DATA OUT FROM THE METER.....     | 18 |
| 7. RS232 PC SERIAL INTERFACE.....                   | 20 |
| 8. OFFSET ( ZERO ) PROCEDURE.....                   | 22 |
| 9. CALIBRATION PROCEDURE.....                       | 22 |
| 10. BATTERY REPLACEMENT.....                        | 25 |
| 11. SYSTEM RESET.....                               | 25 |
| 12. OPTIONAL ACCESSORIES.....                       | 26 |

# 1. FEATURES

- \* Innovative feature with built-in automatic temperature compensation factor adjustable between 0 to 5.0% per °C.
- \* Wide range, 200 uS/2 mS/20 mS/200 mS.
- \* Selecting " 0% per °C " of Temp. Coefficient Adjust, allows you to take uncompensated conductivity readings ( absolute conductivity measurement ).
- \* Temperature compensation range : 0 to 50 °C.
- \* Carbon rod electrode for long life.
- \* Conductivity measurement ( uS, mS ) or TDS ( Total Dissolved Solids, PPM ) can be selected.
- \* Auto range or manual range can be selected.
- \* Real time data logger, build in clock ( hour-min.-sec., year-month-date ).
- \* Auto or manual data record, 16,000 Data logger no.
- \* Wide sampling time adjustment range from two seconds to 8 hours 59 minutes 59 seconds.
- \* RS232 computer interface.
- \* Can default auto power off or manual power off.
- \* Super large LCD display with contrast adjustment for best viewing angle.
- \* Data hold, record max. and min. reading.
- \* Power by UM3 ( 1.5 V ) x 4 batteries or DC 9V adapter.
- \* RS232 PC serial interface.
- \* Separate probe, easy for operation of different measurement environment.
- \* Wide applications: water conditioning, aquariums, beverage, fish hatcheries, food processing, photography, laboratory, paper industry, plating industry, quality control, school & college, water conditioning.

## 2. SPECIFICATIONS

### *2-1 General Specifications*

|                              |                                                                                                                                                                                                                                           |                                                                                                         |
|------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|
| Circuit                      | Custom one-chip of microprocessor LSI circuit.                                                                                                                                                                                            |                                                                                                         |
| Display                      | LCD size : 58 mm x 34 mm.                                                                                                                                                                                                                 |                                                                                                         |
| Measurement                  | * Conductivity ( uS, mS )<br>* TDS ( Total Dissolved Solids, PPM )<br>* Temperature ( °C, °F)                                                                                                                                             |                                                                                                         |
| Temperature Compensation     | Automatic from 0 to 60 °C (32 - 140 °F), with temperature compensation factor variable between 0 to 5.0% per C.                                                                                                                           |                                                                                                         |
| Conductivity Probe Structure | Carbon rod electrode for long life.                                                                                                                                                                                                       |                                                                                                         |
| Sampling Time of Data Logger | Manual                                                                                                                                                                                                                                    | Push the data logger button once will save data one time.<br><i>@ Set the sampling time to 0 second</i> |
|                              | Auto                                                                                                                                                                                                                                      | 2 sec to 8 hour 59 min. 59 sec.                                                                         |
| Data Hold                    | Freeze the display reading.                                                                                                                                                                                                               |                                                                                                         |
| Memory Recall                | Maximum & Minimum value.                                                                                                                                                                                                                  |                                                                                                         |
| Power off                    | Auto shut off saves battery life or manual off by push button.<br><i>@ Can default auto power or manual power off.</i><br><i>@ When default auto power function, power will off automatically after 10 min., if no button be pressed.</i> |                                                                                                         |

|                                          |                                                                                                                                                                                   |
|------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Sampling Time of display                 | Approx. 1 second.                                                                                                                                                                 |
| Data Output                              | RS 232 PC serial interface.                                                                                                                                                       |
| Operating Temperature                    | 0 to 50 °C . - Main instrument.<br>0 to 60 °C - Conductivity probe only.                                                                                                          |
| Operating Humidity                       | Less than 80% R.H.                                                                                                                                                                |
| Power Supply<br><i>* main instrument</i> | DC 1,5 V battery ( UM3 ) x 4 PCs,<br>( Heavy duty type ).<br>DC 9V adapter input.<br><i>@ AC/DC power adapter is optional.</i>                                                    |
| Power Supply<br><i>* clock module</i>    | DC 3V silver battery.<br>Type : CR2032.                                                                                                                                           |
| Power Current                            | Approx. DC 15.2 mA                                                                                                                                                                |
| Weight                                   | 425 g/ 0.94 LB. <i>@ Battery is included.</i>                                                                                                                                     |
| Dimension                                | <i>Main instrument :</i><br>203 x 76 x 38 mm<br><i>Conductivity PROBE :</i><br>Round, 22 mm Dia. x 120 mm length.                                                                 |
| Accessories Included                     | Instruction manual.....1 PC<br>Conductivity probe.....1 PC<br>DC 3V silver battery, CR2032.....1 PC<br>Carrying case.....1 PC                                                     |
| Optional Accessories                     | * 1.413 mS Conductivity Standard Solution<br>* AC to DC 9V adapter.<br>* RS232 cable, UPCB-02.<br>* Data Acquisition software, SW-U801-WIN.<br>* Data Logger software, SW-DL2005. |

## **2-2 Electrical Specifications (23± 5 °C)**

### **A. Conductivity**

| <b>Range</b>                                                                                                                                                                                                                                                                                                            | <b>Measurement</b> | <b>Resolution</b> | <b>Accuracy</b>                       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-------------------|---------------------------------------|
| 200 uS                                                                                                                                                                                                                                                                                                                  | 0 to 200.0 uS      | 0.1 uS            | ± (2% F.S.+1d)<br>* F.S. - Full scale |
| 2 mS                                                                                                                                                                                                                                                                                                                    | 0.2 to 2.000 mS    | 0.001 mS          |                                       |
| 20 mS                                                                                                                                                                                                                                                                                                                   | 2 to 20.00 mS      | 0.01 mS           |                                       |
| 200 mS                                                                                                                                                                                                                                                                                                                  | 20 to 200.0 mS     | 0.1 mS            |                                       |
| <p>* <i>Temperature Compensation :</i><br/> <i>Automatic from 0 to 60 °C ( 32 - 140 °F ), with temperature compensation factor variable between 0 to 5.0% per C.</i></p> <p>* <i>The accuracy is specified under measurement value ≤ 100 mS.</i></p> <p>* <i>mS - milli Simens                      * @ 23± 5°C</i></p> |                    |                   |                                       |

### **B. TDS ( Total Dissolved Solids )**





| <b>Range</b>                                                                                                                                                                                                                                                                                                                       | <b>Measurement</b>    | <b>Resolution</b> | <b>Accuracy</b>                       |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------|---------------------------------------|
| 200 PPM                                                                                                                                                                                                                                                                                                                            | 0 to 132 PPM          | 0.1 PPM           | ± (2% F.S.+1d)<br>* F.S. - Full scale |
| 2,000 PPM                                                                                                                                                                                                                                                                                                                          | 132 to 1,320 PPM      | 1 PPM             |                                       |
| 20,000 PPM                                                                                                                                                                                                                                                                                                                         | 1,320 to 13,200 PPM   | 10 PPM            |                                       |
| 200,000 PPM                                                                                                                                                                                                                                                                                                                        | 13,200 to 132,000 PPM | 100 PPM           |                                       |
| <p>* <i>Temperature Compensation :</i><br/> <i>Automatic from 0 to 60 °C ( 32 - 140 °F ), with temperature compensation factor variable between 0 to 5.0% per °C.</i></p> <p>* <i>The accuracy is specified under measurement value ≤ 66,000 PPM.</i></p> <p>* <i>PPM - parts per million                      * @ 23± 5°C</i></p> |                       |                   |                                       |


### **C. Temperature**

| <b>Function</b> | <b>Measuring Range</b> | <b>Resolution</b> | <b>Accuracy</b> |
|-----------------|------------------------|-------------------|-----------------|
| °C              | 0 °C to 60 °C          | 0.1 °C            | 0.8 °C          |
| °F              | 32 °F to 140 °F        | 0.1 °F            | 1.5 °F          |
| * @ 23± 5°C     |                        |                   |                 |

@ Above specification tests under the environment RF Field Strength less than 3 V/M & frequency less than 30 MHz only.

### 3. FRONT PANEL DESCRIPTION






- 3-1 Display
- 3-2 Power Button
- 3-3 HOLD Button ( ESC Button )
- 3-4 REC Button ( Enter Button )
- 3-5 ▲ Up Button
- 3-6 Range Button ( ▼ Down Button )
- 3-7 Send Button ( Clock Button )
- 3-8 SET Button ( Logger Button )
- 3-9 Stand
- 3-10 Battery Compartment/Cover
- 3-11 Tripod Fix Nut
- 3-12 LCD Brightness Adjust VR
- 3-13 System Reset Switch
- 3-14 RS-232 Output Terminal
- 3-15 DC 9V Power Adapter Input Socket
- 3-16 Probe Input Socket
- 3-17 Probe Plug
- 3-18 Sensing head
- 3-19 Probe Handle



## 4. GENERAL MEASURING PROCEDURE

***The meter default function are following :***

- \* The display unit is set to conductivity ( uS, mS ).
- \* The temperature unit is set to °C.
- \* Temp. compensation factor is set to 2.0% per C.
- \* Auto range.
- \* Auto power off.
- \* The sampling time of data logger function is 2 seconds.



#### ***4-1 Conductivity ( $\mu\text{S}$ , $\text{mS}$ ) measurement***

- 1) Install the " Probe Plug " ( 3-17, Fig. 1 ) into the " Probe Input Socket " ( 3-16, Fig. 1 ).
- 2) \* Press and release the " Power Button " ( 3-2, Fig. 1 ) to power on the meter.
  - \* Hold the " Probe Handle " ( 3-19, Fig. 1 ) by hand and let the " Sensing head " ( 3-18, Fig. 1 ) immersed wholly into the measured solution. Shake the probe to let the probe's internal air bubble drift out from the sensing head.

Display will show the conductivity  $\text{mS}$  (  $\mu\text{S}$  ) values. at the same time the left bottom display will show the Temp. value of the measured solution.

#### **Manual range operation**

The meter is default to be used for the auto range mode.

Under the auto range measurement, the bottom right display will show the " Auto Range " indicator.

If intend to let the meter be used under the manual range mode, the procedures are following :

- \* Press the " Range Button " ( 3-6, Fig. 1 ) continuously at least two seconds until the bottom right display show the " Manual Range " Indicator, then release the " Range Button ", now the meter is ready for the manual range operation.
- \* Push the " Range Button " once a while, it can change the range, the range value ( 200  $\mu\text{S}$ , 2  $\text{mS}$ , 20  $\text{mS}$ , 200  $\text{mS}$  ) will show under the measurement value.

- \* If the display shows " - - - - - ", it indicates an overload condition, select the next higher range.
- \* If the display shows " \_ \_ \_ \_ \_ ", it indicates an out-of-range, select the next lower range.
- \* If intend to change the operation mode from Manual range back to Auto range, then Press the " Range Button " ( 3-6, Fig. 1 ) continuously at least two seconds until the bottom right display show the " Auto Range " Indicator, release the " Range Button ". Now the meter is ready for the Auto range mode again.

### **Change the Temp. unit to °F**

If intend to change the Temp. unit from °C to °F, please refer page 16, chapter 5-7 ( Temp. Unit Default Setting )

### **Change the Temp. Coefficient Factor**

The default Temp. compensation factor value is to 2.0% per °C. If intend to change it, please refer page 16, chapter 5-8 ( Temp. Compensation Default Setting ).

#### ***4-2 TDS ( PPM ) measurement***

The measuring procedures are same as above

*4-1 Conductivity ( uS, mS ) measurement,*

except to change the display from uS, mS to PPM.

The detail procedures please refer page 16, chapter 5-8 CD ( uS, mS ), TDS ( PPM ) Default Setting.

### **4-3 Data Hold**

During the measurement, press the " Hold Button " ( 3-3, Fig. 1 ) once will hold the measured value & the LCD will display a " HOLD " symbol.

Press the " Hold Button " once again will release the data hold function.

### **4-4 Data Record ( Max., Min. reading )**

- \* The data record function records the maximum and minimum readings. Press the " REC Button " ( 3-4, Fig. 1 ) once to start the Data Record function and there will be a " REC. " symbol on the display.
- \* With the " REC. " symbol on the display:
  - a) Press the " REC Button " ( 3-4, Fig. 1 ) once, the " REC. MAX. " symbol along with the maximum value will appear on the display.  
If intend to delete the maximum value, just press the " Hold Button " ( 3-3, Fig. 1 ) once, then the display will show the " REC. " symbol only & execute the memory function continuously.
  - b) Press the " REC Button " ( 3-4, Fig. 1 ) again, the " REC. MIN. " symbol along with the minimum value will appear on the display.  
If intend to delete the minimum value, just press the " Hold Button " ( 3-3, Fig. 1 ) once, then the display will show the " REC. " symbol only & execute the memory function continuously.
  - c) To exit the memory record function, just press the " REC " button for 2 seconds at least. The display will revert to the current reading.

#### ***4-5 Data Logger***

The data logger function can save 16,000 measuring data with the clock time ( Real time data logger, build in clock ( hour-min.-sec., year-month-date ).

The data logger procedures are as following :

a) If push the " Logger Button " ( 3-8, Fig. 1 ) once will show the sampling time value on the bottom left display then disappeared.

b) Press the " REC Button " ( 3-4, Fig. 1 ) once to start the Data Record function and there will be a " REC. " symbol on the display.

**c) Auto Data Logger ( Sampling time set from 2 seconds to 8 hours 59 minutes 59 seconds )**

Press the " Logger Button " ( 3-8, Fig. 1 ) once to start the Auto Data Logger function, at the same the bottom right display will show the indicator " Recording.... ", now the Data Logger function is executed. The upper display will show " DATA " indicator along with " REC " marker.

**d) Manual Data Logger ( Sampling time set to 0 second )**

Press the " Logger Button " ( 3-8, Fig. 1 ) once will save the data one time into the memory, at the same time the bottom right display will show the indicator " Recording.... " a while. Now the Data logger function is executed. The upper display will show " DATA " indicator along with " REC " marker.

e) **Memory full**

Under execute the data logger, if the bottom right display show the " Full ", it indicate the memory data already over 16,000 no. and the memory is full.

f) During the Data Logger function is executed, press the " Logger Button " ( 3-8, Fig. 1 ) once will stop to execute the data logger function, the " DATA " indicator will be disappeared.

If press the " Logger Button " ( 3-8, Fig. 1 ) once again will continuous the Data Logger function.

*Remark :*

- 1) If intend to change the data logger sampling time, please refer chapter 5-4.*
- 2) If intend to know the space of balance data numbers into the memory IC, please refer chapter 5-1.*
- 3) If intend to clear the saving data from the memory please refer chapter 5-2.*

## **5. ADVANCED ADJUSTMENT PROCEDURES**

When execute the following Advanced Adjustment Procedures should cancel the " Hold function " and the " Record function " first. The display will not show the " HOLD " and the " REC " marker.

- a. Press the " SET Button " ( 3-8, Fig. 1 ) at least two seconds until the lower display show

|                         |
|-------------------------|
| XXXXX      Memory Space |
|-------------------------|

\* If push the " ESC Button " ( 3-3, Fig. 1 ) will escape the selecting function and return to the normal measuring display.

- b. One by one to press the " Set Button " ( 3-8, Fig. 1 ) once a while to select the ten main function, at the same time lower display will show on the lower display will show on the lower display as :

**Memory Space**  
**Clear Memory**  
**Date/Time Set**  
**Sample Time**  
**Auto Power Off**  
**Temp. Unit**  
**Temp. Comp.**  
**CD, TDS Select**  
**ESC→Finish**

- c. When make Advanced Adjustment Procedure will use the following key buttons :

ESC Button ( 3-3, Fig. 1 ), Enter Button ( 3-4, Fig. 1 )  
▲ Up Button ( 3-5, Fig. 1 ), ▼ Down Button ( 3-6, Fig. 1 )  
SET Button ( 3-8, Fig. 1 ), SEND Button ( 3-7, Fig. 1 )

### **5-1 Check Memory Space**

To check the balance data numbers that exist into the memory ( allow memorize data no. ).

|                         |
|-------------------------|
| XXXXX      Memory Space |
|-------------------------|

@XXXXX is the balance data numbers, for example  
XXXXX=15417.

### **5-2 Clear Memory**

- \* To delete the existing save data numbers from the memory.
- \* Push ENTER Button once, then push ENTER Button to confirm.
- \* Press the ESC Button once to quite and return to the main measurement manual.

### **5-3 Date/Time Setting**

- \* Use ▲ Up Button, ▼ Down Button and Enter ( → ) Button to select the expect Date ( year-month-date ) and the time ( HOUR-MIN.-SEC.).
- \* After finish the Date/Time adjustment, Push the " Enter Button " , then press the " ESC Button " will quite and save the clock data into the memory.



#### ***5-4 Sample Time Setting***

- \* Use ▲ Up Button, ▼ Down Button and Enter (→) Button to select the expect Sample Time ( HOUR-MIN.-SEC.).
- \* After finish the Sample Time adjustment, Push the " Enter Button " , then press the " ESC Button " will quite and save the clock data into the memory.

#### ***5-5 Auto Power Off Default Setting***

- \* Use ▲ Up Button, ▼ Down Button to select " 1 " or " 0 ".

|                                                         |
|---------------------------------------------------------|
| <b>1 = Auto power On.</b><br><b>0 = Auto power Off.</b> |
|---------------------------------------------------------|

- \* After finish the Auto Power Off adjustment, push the " Enter Button " , then press the " ESC Button " will quite and return to the normal measurement display.

#### ***5-6 Temp. Unit Default Setting***

- \* Use ▲ Up Button, ▼ Down Button to select " 1 " or " 0 ".

|                                |
|--------------------------------|
| <b>1 = °F</b><br><b>0 = °C</b> |
|--------------------------------|

- \* After finish the Temperature unit adjustment, push the " Enter Button " , then press the " ESC Button " will quite and return to the normal measurement display.

**5-7 Temp. Compensation Factor Default Setting.**

- \* Use ▲ Up Button, ▼ Down Button and SEND (→) Button to select the Temp. Compensation Factor value.
- \* After setting the desired value, push the " Enter Button " , then press the " ESC Button " will quite and return to the normal measurement

**5-8 CD ( uS, mS ), TDS ( PPM ) Default Setting**

- \* Use ▲ Up Button, ▼ Down Button to select the " 1 " or " 0 " .

|                   |
|-------------------|
| <b>0 = uS, mS</b> |
| <b>1 = PPM</b>    |

- \* After finish the unit ( CD, TDS ) adjustment, push the " Enter Button " , then press the " ESC Button " will quite and return to the normal measurement display.


**5-9 Escape from the SETTING function**

Press the " ESC Button " once a while will quite and return to the normal measurement display.

## 6. HOW TO SEND THE DATA OUT FROM THE METER

- 1) If intend to send the data out from the meter, it should cancel the " Hold function " and the " Record function " first. The display will not show the " HOLD " and the " REC " marker.
- 2) Press the " SEND Button " ( 3-7, Fig. 1 ) at least 2 seconds until the bottom right display show " Transmit mode ", then release the button.

**LCD display will show the fowling screen alternately.**




**Use ▲ Up Button, ▼ Down Button to select the different data memory block no. ( 1 to 250 ).**

**The meter can save 16,000 data max. , those data will saved into 250 memory block max.**

\* One " Memory Block " means :

The data that save into one routine Data Logger procedures ( Push " REC " button , following push the " Logger " button to save the data, the display will show the " REC " and " DATA " . After save the data push the " Logger " button, following push the " REC " button, will exist the Data Logger function. The " REC " and " DATA " indicator of LCD will be disappeared ). Please refer Chapter 4-6, page 12.



- 3) Until the desired Memory Block no. be selected.  
Push the " Send Button " ( 3-5, Fig. 1 ) once, the data in the Memory Block will send out.  
During the data send out, the bottom right display will show the " Sending Data ! " indicator. When data already send out completely, the bottom right display will show the Transmit mode " indicator again.
- 5) Push the " ESC Button " ( 3-3, Fig. 1 ) will exist the data sending function and return to the normal display.

**Remarks :**

***@ If intend up load the data to the computer, then should connect the RS232 cable ( optional, model : UPCB-02) and apply the Data Logger software ( optional, Model : SW-DL2005 ).***


***@ When sending the data, each time just can send one Memory Block data out. for example block 1 data, block 2 data... or block 250 data.***

## 7. RS232 PC SERIAL INTERFACE

The instrument has RS232 PC serial interface via a 3.5 mm terminal ( 3-14, Fig. 1 ).

The data output is a 16 digit stream which can be utilized for user's specific application.

A RS232 lead with the following connection will be required to link the instrument with the PC serial port.



The 16 digits data stream will be displayed in the following format :

D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0

**Each digit indicates the following status :**

|           |                                                                                                                     |
|-----------|---------------------------------------------------------------------------------------------------------------------|
| D0        | End Word = 0D                                                                                                       |
| D1 & D8   | Display reading, D1 = LSD, D8 = MSD<br>For example :<br>If the display reading is 1234, then D8 to D1 is : 00001234 |
| D9        | Decimal Point(DP), position from right to the left<br>0 = No DP, 1 = 1 DP, 2 = 2 DP, 3 = 3 DP                       |
| D10       | Polarity<br>0 = Positive 1 = Negative                                                                               |
| D11 & D12 | Annunciator for Display<br>uS = 13      mS = 14      PPM = 19                                                       |
| D13       | When send the upper display data = 1<br>When send the lower display data = 2                                        |
| D14       | 4                                                                                                                   |
| D15       | Start Word = 02                                                                                                     |

**RS232 setting**

|              |             |
|--------------|-------------|
| Baud rate    | 9600        |
| Parity       | No parity   |
| Data bit no. | 8 Data bits |
| Stop bit     | 1 Stop bit  |

## **8. OFFSET ( ZERO ) PROCEDURE**

If no signal out from the probe ( probe's sensing head is not immersed into the measuring solution ) but the display exist certain value ( not zero ), it can make the offset ( zero ) adjustment as :

- 1) To let The " Sensing head " ( 3-18, Fig, 1 ) is not immersed into the measurement solution and dry completely.
- 2) Press the " ▲ Up Button " ( 3-5, Fig. 1 ) " continuously at least two seconds until the meter generate a " beeper " sound, at the same time the display will change to zero value.

## **9. CALIBRATION PROCEDURE**

The meter has been calibrated carefully during manufacture. However, it may be necessary to re-calibrate periodically. Particularly if the instrument is used for a long period or if the conductivity electrode is changed.

To re-calibrate the instrument, follow the procedures shown below :


- 1) Prepare a " 1.413 mS Calibration Solution " ( optional, or other standard conductivity solution can also be done for the calibration procedure ).
- 2) Power ON the meter  
Select the auto range mode.



- 3) Immerse the " Sensing Head "(3-18, Fig. 1)  
into the calibration solution up to the immersion level.
- 4) To press the follow two buttons at the same time.

**HOLD Button ( 3-3, Fig. 1 )**  
**REC Button ( 3-4, Fig. 1 )**

The bottom display will show " 0:Temp., 1:CD ", then  
release the two buttons, The LCD will show  
for example as :




The up big display will show the conductivity value  
that measured from the standard solution.

- 5) Use ▲ Up Button, ▼ Down Button to select the  
" 1 " or " 0 ".


**1 = Conductivity calibration**  
**0 = Temp. calibration**

For the conductivity calibration, select " 1 ", then  
press the " Enter Button " ( 3-4, Fig. 1 ).

The display will show for example as :



Use ▲ Up Button, ▼ Down Button to select the desired calibration value, for example : 1.413




Until desired value is selected, press " Enter Button " twice to entry the data, then the display will return to the normal display and finish the calibration procedures.

**Remark :**

***For each range of 200 uS, 2 mS, 20 mS, 200 mS can entry one calibration value, that means each range can do its independent calibration procedures.***

## 10. BATTERY REPLACEMENT

1) The time to change the UM3 ( 1.5 V ) x 4 PCs

When the left corner of LCD display show "  ", it is necessary to replace the batteries ( UM3/1.5 V x 4 PCs ).

The time to change the CR2032 ( 3V silver battery )

When the clock is not accurate or power off the meter then on, the clock time is disappeared or garbled, it is necessary to replace the battery ( CR2032 )

- 2) Slide the " Battery Cover " ( 3-10, Fig. 1 ) away from the instrument and remove the battery.
- 3) Replace with batteries ( UM3/1.5 V x 4 PCs or CR2032 ) and reinstate the cover.
- 4) Make sure the battery cover is secured after changing the battery.

## 11. SYSTEM RESET

If the meter happen the troubles such as :

*CPU system is garbled ( for example, the key button can not be operated..... ).*

Then make the system RESET will fix the problem.  
The system RESET procedures will be either following method :

- 1) Slide the " Probe Lock Switch/System On/Off Switch " from the On to Off, then On again.
- 2) Or during the Power On, used a pin tool to push the " System Reset Switch " ( 3-13, Fig. 1 ) once a while.

## 12. OPTIONAL ACCESSORIES

|                                          |                                                                                                                                                                                                                                                                                                                                                          |
|------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| RS232 cable<br>UPCB-02                   | * Isolated RS232 cable.<br>* Used to connect the meter to the computer                                                                                                                                                                                                                                                                                   |
| Data Logger software<br>SW-DL2005        | * Software the used to download the data logger ( data recorder ) from the meter to computer.                                                                                                                                                                                                                                                            |
| Data Acquisition software<br>SW-U801-WIN | * The SW-U801-WIN is a multi displays ( 1/2/4/6/8 displays ) powerful application software, provides the functions of data logging system, text display, angular display, chart display, data recorder high/low limit, data query, text report, chart report..<br>.xxx.mdb data file can be retrieved for EXCEL, ACCESS., wide intelligent applications. |

|                              |                                                 |
|------------------------------|-------------------------------------------------|
| Calibration<br>Cal. Solution | 1.413 mS calibration solution.<br>Model : CD-14 |
|------------------------------|-------------------------------------------------|