VIBRATION CONTROLLER/MONITOR Model : PVB-8219





Your purchase of this VIBRATION CONTROLLER/ MONITOR marks a step forward for you into the field of precision measurement. Although this vibration controller is a complex and delicate instrument, its durable structure developed. Please read the following instructions carefully and always keep this manual within easy reach.

OPERATION MANUAL

Caution Symbol





Caution :

* Risk of electric shock !

Caution :

- * Do not use fingers or any tool to touch the Wire Terminals.
- Do not apply the relay contact load current > 0.5 Amp.
- * The instrument contains no user serviceable parts and should not be opened by the user.
- * Repair or after service should be done by a qualified technician only.
- * Power supply should apply the correct ACV power voltage
- * Cleaning Only use the dry cloth to clean the plastic case !

* Equipment protectted throughout by Double Insulation or Reinforced Insulation.

Environmental Condition

- Comply with EN61010.
 Transient overvoltage at Mains Supply 2500V.
- * Pollution Degree 2.
- * Altitude up to 2000 meters.
- * Indoor use.
- * Relative humidity 80% max.

TABLE OF CONTENTS

FEATURES	1
SPECIFICATIONS	2
2-1 General Specifications	2
2-2 Electrical Specifications	4
FRONT PANEL DESCRIPTION	6
MEASURING PROCEDURE	7
4-1 Indicator Description	7
4-2 Terminal layout	7
4-3 Terminal connection	8
4-4 VIBRATION Measurement	8
4-5 1st layer setting procedures	9
4-6 2nd layer setting procedures	11
RS232 PC SERIAL INTERFACE	15
SYSTEM RESET	17
SENSITIVITY RELATIVE to the reference sensitivity at 80 Hz ,	
according ISO 2954	17
THE ADDRESS OF AFTER SERVICE CENTER	18
	FEATURES. SPECIFICATIONS. 2-1 General Specifications. 2-2 Electrical Specifications. FRONT PANEL DESCRIPTION. MEASURING PROCEDURE. 4-1 Indicator Description 4-2 Terminal layout 4-3 Terminal connection. 4-4 VIBRATION Measurement 4-5 1st layer setting procedures. 4-6 2nd layer setting procedures. RS232 PC SERIAL INTERFACE. SYSTEM RESET. SENSITIVITY RELATIVE to the reference sensitivity at 80 Hz , according ISO 2954. THE ADDRESS OF AFTER SERVICE CENTER.

1. FEATURES

- * Applications for industrial vibration monitoring : All industrial machinery vibrates. The level of vibration is a useful guide to machine condition. Poor balance,misalignment & looseness of the structure will cause the vibration level increase, it is a sure sign that the
- * Frequency range 10 Hz 1 kHz, sensitivity relative meet ISO 2954.
- * Professional vibration meter supply with vibration sensor & magnetic base, full set.
- * Metric & Imperial display unit
- * Acceleration, Velocity, Displacement measurement.
- * Separate vibration probe with magnetic base, easy operation.
- * Wide frequency range.
- * Control setting, Hi/Lo alarm setting.
- * Control relay output, alarm relay output.
- * Control Relay will make action when the reading value reach to control value.
- * Alarm Relay will make action when the reading value reach to high/low alarm value.
- * Hysteresis value setting for control and alarm function.
- * Large red LED display, high brightness and easy to read.
- * RS232 computer interface, send out the vibration data .
- * Optional data acquisition software.
- * Microprocessor circuit ensures high accuracy and provides special functions and features.
- * Standard 96 X 48 mm DIN case.

2. SPECIFICATIONS

2-1 General Specifications

Circuit	Custom one-chip of microprocessor LSI circuit.			
Display	4 digits red LED, digit size : 14 mm.			
Measurement	Velocity, Acceleration	Velocity, Acceleration, Displacement		
Function	Acceleration, Velocity :	Acceleration, Velocity : RMS		
	Displacement : p-p ((peak-peak)		
Display Unit	Measurement	Metric	Imperial	
	Acceleration	meter/s^2	ft/s^2	
	Velocity	mm/s	inch/s	
	Displacement	mm	inch	
Frequency	10 Hz to 1 KHz		•	
range	ge * Sensitivity relative during the			
	frequency range meet ISO 2954			
	Refer to table 1, p	age 17		
Offset adjust	It can make the internal Offset setting			
Gain adjust	It can make the internal Gain setting			
Sampling Time	pprox. 1 second.			
Setting Function	1st layer setting	CtLo (Control Ic	w limit)	
	procedures	CtHi (Control hi	gh limit)	
		ALLo (Alarm low limit)		
		ALHi (Alarm hig	ıh limit)	
	Second layer setting	FiLt (Digital filte	r)	
	procedures	CtHy (Control h	ysteresis set)	
		ALHy (Alarm hy	rsteresis set)	
		oFSt (Offset adj	justment)	
		GAin (Gain adju	istment)	
		Unit (Unit set)		

Relay outputs	Number	2 relays
	Function	Relay 1 :
		Control relay.
		Relay 2 :
		High/Low alarm relay.
	Max load	0.5 ACA/250 ACV
		0.5 DCA/24 DCV
		* Do not apply the relay
		contact load current
		> 0.5 A, other wise the
		relay may be damaged
		permanently without
		warranty.
Data Output	RS 232 PC serial in	terface.
Operating	0 to 50 ℃.	
Temperature	* Meter	
Operating	Less than 80% R.H.	
Humidity	* Meter	
Power Supply	90 to 260 ACV, 50/6	60 Hz.
Power	Approx. 2.6 VA/AC	110V.
Consumption	Approx. 5.1 VA/AC	220V.
Weight	282 g/ 0.62 LB.	* Meter only.
Dimension	DIN size : 96 x 48 m	ım.
	Depth : 110 mm.	
Accessories	Instruction manual	1 PC
Included	Case holder with sc	rew 2 PCs
	Vibration sensor with	h cable 1 PC
	Magnetic base	1 PC
Optional	* Data Acquisition	software,
Accessories	SW-U801-WIN.	
	* RS232 cable, UF	PCB-02.
	* USB cable, USB	-01.
	* Real time SD card	l data logger DL-9602SD

2-2 Electrical Specifications (23±5 °C)

Acceleration (RMS)

Unit	m/s^2
Range	0.5 to 199.9 m/s^2
Resolution	0.1 m/s^2
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 \pm 5 $^{\circ}\!$
Calibration	50 m/S^2(160 Hz)
Point	

Unit	ft/s^2
Range	2 to 656 ft/s^2
Resolution	1 ft/s^2
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 ± 5 ℃
Calibration	50 m/S^2 (160 Hz)
Point	

Velocity (RMS)

Unit	mm/s
Range	0.5 to 199.9 mm/s
Resolution	0. 1 mm/s
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 \pm 5 $^{\circ}$ C
Calibration	50 mm/s(160 Hz)
Point	

Unit	inch/s
Range	0.02 to 7.87 inch/s
Resolution	0.01 inch/s
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 ± 5 ℃
Calibration	50 mm/s(160 Hz)
Point	

Remark :

RMS : To measure the true RMS value.

Displacement (p-p)

Unit	mm
Range	1.999 mm
Resolution	0.001 mm
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 \pm 5 $^{\circ}$ C
Calibration	0.141 mm (160 Hz)
Point	

Unit	inch
Range	0.078 inch
Resolution	0.001 inch
Accuracy	±(5 % + 2 d) reading
	@ 160 Hz, 80 Hz, 23 ± 5 ℃
Calibration	0.141 mm (160 Hz)
Point	

Remark :

р-р :

To measure the Peak to Peak value.

@ Above specification tests under the environment RF Field Strength less than 3 V/M & frequency less than 30 MHz only.

3. FRONT PANEL DESCRIPTION







Fig. 1

- 3-1 Display
- 3-2 PV (process value) indicator
- 3-3 SV (set value) indicator
- 3-4 Set Button
- 3-5 ▼ Button
- 3-6 ▲ Button
- 3-7 Function Button
- 3-8 Control relay indicator
- 3-9 Alarm relay indicator
- 3-10Acceleration unit indicator
- 3-11 Velocity unit indicator

- 3-12 Displacement unit indicator
- 3-13Wire terminals
- 3-14 RS232 output terminal
- 3-15 BNC input socket
- 3-16 Case holder
- 3-17 Magnetic base
- 3-18 Vibration sensor
- 3-19 Input socket of vibration sensor
- 3-20 Mini plug of cable
- 3-21Sensor cable
- 3-22 Cable BNC plug

4. MEASURING PROCEDURE

4-1 Indicator Description

- A. Metric units are red Indicators:
 - 1) Acceleration: m/s²
 - 2) Velocity: mm/s
 - 3) Displacement: mm
- B. Inch units are yellow. Indicators
 - 1) Acceleration: ft/s²
 - 2) Velocity: inch/s
 - 3) Displacement: inch
- C. Setting Indicators:
 - 1) PROCESS VALUE(PV)
 - 2) Lit during normal test will be light.
 - 3) Lights up when the up / down key is not pressed in setup mode
- D. SET VALUE(SV):
 - When the upper and lower values are adjusted, the light will be on and the PV will not turn on until the SET key is pressed. The setting value will be stored and the indicator will be off.
- E. Control Indicators:
 - 1) CONTROL RELAY (OUT): This light is on when Control RELAY ON, otherwise OFF
 - 2) ALARM RELAY (ALM): When the ALARM RELAY ON , the light will be on, otherwise OFF .

4-2 Terminal layout





4-3 Terminal connection

1) Input the ACV power ($90\ to\ 260\ ACV$) to T1, T2.



Do not input the over voltage to the AC input terminals.

2) Connect the " Alarm Relay " output from T3, T4. Connect the " Control Relay " output from T5, T6.

4-4 VIBRATION Measurement

A. PREPARE

- 1) Plug in the "Mini plug of cable " (3-20, Fig. 1) to the "Input socket of vibration sensor " (3-19, Fig. 1).
- 2) Plug in the " Cable BNC Plug " (3-22, Fig. 1) to the " BNC Input Socket " (3-15, Fig. 1).
- Meter connect to ACV POWER ,Press the Function key(3-7 ,Fig 1) to select ACC(3-10 Fig.1) or VEL(3-11,Fig, 1) or Displacment (3-12 ,Fig. 1)The " Display " (3-1, Fig. 1) will show the vibration test value,

- 1. If the surface material of measuring article is not the ferrous material, hold the vibration sensor (3-18, Fig 1) by hand & touch the sensor to the surface of the measuring article,
- If the surface material of measuring article is the ferrous material, connect "Vibration sensor " (3-18, Fig. 1) with the "Magnetic base " (3-17, Fig. 1)Put the whole unit (Vibration sensor and Magnetic base) to the surface of measuring article.
- * Please do not use the finger or hand to touch the "Sensor cable " (3-21, Fig. 1).

B. Unit select

Press and hold the SET Button(3-4, Fig. 1) > 2 sec. into setting then short press SET Button (3-4, Fig. 1) 5 times, The screen will stay in Unit use " \triangle (3-6, Fig.1)" $\$ " ∇ (3-5, Fig.1)" Button select Metric or Imperial then short press "SET Button " once, wii be save select unit, short press "SET Button " once again , will back to measure screen.

Metric unit indicater light color is red.

Imperial unit indicater light color is yellow.

Measurement	Metric	Imperial
Acceleration	m/s^2	ft/s^2
Velocity	mm/s	inch/s
Displacement	mm	inch

4-5 1st layer setting procedures

CtLo	Control Low Limit Value Setting
CtHI	Control High Limit Value Setting
ALLo	Alarm Low Limit Value Setting
ALHI	Alarm High Limit Value Setting

A. Control Low Limit Value Setting

- 1) Press the "Set Button " (3-4, Fig. 1) once, the Display will show "CtLo ", now the meter is ready for the Control Low Limit Value Setting.
- 2) In " CtLo " screen, short press Function button(3-7, Fig. 1) to select Acceleration or velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" button once, display will show control value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" button to adjustment control limit value, then short press the "SET Button " once ,will saved the setting value and back to " CtLo " screen.

- * When adjust the value, the "SV indicator " (3-3, Fig. 1) will light.
- * Under Display show " LoLt ", if " Acceleration indicator " (3-10, Fig. 1) is lit, meter is ready for " Acceleration Low Limit " setting.
- * Under Display show " LoLt ", if " Velocity indicator " (3-11, Fig. 1) is lit, meter is ready for " Velocity Low Limit " setting.

- * Under Display show " LoLt ", if " Displacement indicator (3-12, Fig. 1) " is lit, meter is ready for " Displacement Low Limit " setting.
- * The function of " Low Limit value " setting, refer to page 13, Fig. 3.

B. Control High Limit Value Setting

- 1) Finish " CtLo"setting, Press the " Set Button " (3-4, Fig. 1) once, the Display will show " CtHI ", now the meter is ready for the Control High Limit Value Setting.
- 2) In "CtHI " screen, short press Function Button(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show control Value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment control Limit Value, then short press the "SET Button " once ,will saved the setting value and back to " CtLo " screen.

Remark :

- * When adjust the value, the "SV indicator " (3-3, Fig. 1) will light.
- * Under Display show " HILt ", if " Acceleration indicator " (3-10, Fig. 1) is lit, meter is ready for " Acceleration Low Limit " setting.
- * Under Display show " HILt ", if " Velocity indicator " (3-11, Fig. 1) is lit, meter is ready for " Velocity Low Limit " setting.
- * Under Display show " HILt ", if " Displacement indicator (3-12, Fig. 1) " is lit, meter is ready for " Displacement Low Limit " setting.
- * The function of " High Limit value " setting, refer to page 13, Fig. 3.

C. Alarm Low Limit Value Setting

- 1) Finish " CtHI"setting, Press the " Set Button " (3-4, Fig. 1) once, the Display will show " ALLo ", now the meter is ready for the Alarm Low Limit Value Setting.
- 2) In " ALLo " screen, short press Function Button(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show control Value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment control Limit Value, then short press the "SET Button " once ,will saved the setting value and back to " ALLo " screen.

Remark :

* When adjust the value, the "SV indicator " (3-3, Fig. 1) will light.

- * Under Display show " ALLo ", if " Acceleration indicator " (3-10, Fig. 1) is lit, meter is ready for " Acceleration Low Limit " setting.
- * Under Display show " ALLo ", if " Velocity indicator " (3-11, Fig. 1) is lit, meter is ready for " Velocity Low Limit " setting.
- * Under Display show " ALLo ", if " Displacement indicator (3-12, Fig. 1) " is lit, meter is ready for " Displacement Low Limit " setting.
- * The function of " Alarm Low Limit value " setting, refer to page 14, Fig. 4.

D. Alarm High Limit Value Setting

- 1) Finish " ALLo"setting, Press the " Set Button " (3-4, Fig. 1) once, the Display will show " ALHI ", now the meter is ready for the Alarm High Limit Value Setting.
- 2) In " ALHI " screen, short press "Function Button"(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show control Value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment control Limit Value, then short press the "SET Button " once ,will saved the setting value and back to " ALHI " screen.

Remark :

- * When adjust the value, the "SV indicator " (3-3, Fig. 1) will light.
- * Under Display show " ALHI ", if " Acceleration indicator " (3-10, Fig. 1) is lit, meter is ready for " Acceleration Low Limit " setting.
- * Under Display show " ALHI ", if " Velocity indicator " (3-11, Fig. 1) is lit, meter is ready for " Velocity Low Limit " setting.
- * Under Display show " ALHI ", if " Displacement indicator (3-12, Fig. 1) " is lit, meter is ready for " Displacement Low Limit " setting.
- * The function of " Alarm High Limit value " setting, refer to page 14, Fig. 4.

4-6 2nd layer setting procedures

FiLt	Digital Filter Value Setting
CtHy	Control Hysteresis Value Setting
ALHy	Alarm Hysteresis Value Setting
oFSt	Offset Value Setting
Gain	Gain Value Setting
Unit	Unit Setting

A. Digital Filter Value

- Press the "Set Button" (3-4, Fig. 1) continuously at least two seconds, the "Display "will show "FiLt ", now the meter is ready for the Digital Filter Value Setting.
- 2) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show digital value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Digital Filtet Value, then short press the "SET Button " once ,will saved the setting value and back to " FiLt " screen.

Remark :

- * When adjust the value, the "SV indicator " (3-3, Fig. 1) will light.
- * Digital Filter Value range 1 to 100, Factory default setting Value 3.

B. Control Hysteresis Value Setting

- Finish "FiLt"setting, Press the "Set Button " (3-4, Fig. 1) continuously at least two seconds, the "Display " will show "CtHy ", now the meter is ready for the Control Hysteresis Value Setting.
- 2) In " CtHy " screen, short press "Function Button"(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show digital value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Control Hysteresis Value, then short press the "SET Button " once ,will saved the setting value and back to " CtHy " screen.

- * When adjust the Control Hysteresis value, the "SV indicator " (3-3, Fig. 1) will light.
- * The function of " Control Hysteresis value " setting, refer to page 13, Fig. 3.



For example :

Control High limit value : 39.0

Control Low limit value : 10.0

Control Hysteresis value : 0.5

- a. When measurement value \geq 39.0 The Control relay will On ,when measuring value \leq 38.5 The Control relay will Off .
- b. When measurement value ≤ 10.0 The Control relay will On ,when measuring value ≥ 10.5 The Control relay will Off .

C. Alarm Hysteresis Value Setting

- 1) Finish " CtHy"setting, Press the " Set Button " (3-4, Fig. 1) continuously at least two seconds, the " Display " will show " ALHy ", now the meter is ready for the Alarm Hysteresis Value Setting.
- 2) In " ALHy " screen, short press "Function Button"(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show digital value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Alarm Hysteresis Value, then short press the "SET Button " once ,will saved the setting value and back to " ALHy " screen.

- When adjust the Alarm Hysteresis value, the "SV indicator " (3-3, Fig. 1) will light.
- * The function of " Alarm Hysteresis value " setting, refer to page 14, Fig. 4.



For example :

Alarm High limit value : 10.0

Alarm Low limit value : 2.0

Alarm Hysteresis value : 0.5

- a. When measurement value \ge 10.0 The alarml relay will On ,when measuring value \le 9.5 The alarm relay will Off .
- b. When measurement value ${\leq}2.0$ The alarml relay will On ,when measuring value ${\geq}$ 2.5 The alarm relay will Off .

D. Offset Value Setting

- 1) Finish " ALHy"setting, Press the " Set Button " (3-4, Fig. 1) continuously at least two seconds, the " Display " will show " oFSt ", now the meter is ready for the Offset Valu Setting.
- 2) In " oFSt " screen, short press "Function Button"(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- 3) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show digital value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Offset value, then short press the "SET Button " once ,will saved the setting value and back to " oFSt " screen.

Remark :

- * When adjust the Offset Value, the "SV indicator" (3-3, Fig. 1) will light.
- * The function of " Offset Value " setting, Factory default setting 0.0

E. Gain Value Setting

1) Finish " oFSt"setting, Press the " Set Button " (3-4, Fig. 1) continuously at least two seconds, the " Display " will show " Gain ", now the meter is ready for the Gain Value Setting.

- 2) In " Gain " screen, short press "Function Button"(3-7, Fig. 1) to select Acceleration or Velocity or Displacement Function .
- Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show digital value ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Gain Value, then short press the "SET Button " once ,will saved the setting value and back to " Gain " screen.

Remark :

- * When adjust the Gain Value, the "SV indicator " (3-3, Fig. 1) will light.
- * The function of " Gain Value " setting, Factory default setting Value 1.000

F. Unit Setting

- Finish " Gain"setting, Press the " Set Button " (3-4, Fig. 1) continuously at least two seconds, the " Display " will show " Unit ", now the meter is ready for the Unit Setting Setting.
- 2) Press the "▲(3-6,Fig.1)"or"▼(3-5,Fig.1)" Button once, display will show SI or IMPE ,then use "▲(3-6,Fig.1)"and"▼(3-5,Fig.1)" Button to adjustment Unit Setting, then short press the "SET Button " once ,will saved the setting value and back to " Unit " screen.

Remark :

- * When adjust the Unit Setting, the "SV indicator " (3-3, Fig. 1) will light.
- * The function of " Unit Setting " setting, Factory default setting Metric .

5. RS232 PC SERIAL INTERFACE

The instrument has RS232 PC serial interface via a 3.5 mm terminal (3-14, Fig. 1).

The data output is a 16 digit stream which can be utilized for user's specific application.

A RS232 lead with the following connection will be required to link the instrument with the PC serial port.



The 16 digits data stream will be displayed in the following format :

D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0

Each digit indicates the following status :

D15	Start Word				
D14	4				
D13	When send the upper display data = 1				
	When send the lower display data = 2				
D12 & D11	Annunciator for Display				
	m/s^2 =92	mm/s = 93	mm = 94		
	Ft/s^2 =97	inch/s =98	inch =96		
D10	Polarity				
	0 = Positive 1 = Negative				
D9	Decimal Point(DP), position from right to the				
	left				
	0 = No DP, 1= 1 DP, 2 = 2 DP, 3 = 3 DP				
D8 to D1	Display reading, D8 = MSD, D1 = LSD.				
	If the display reading is 1234, then D8 to				
	D1 is : 00001234				
D0	End Word				

RS232 setting

Baud rate	9600
Parity	No parity
Data bit no.	8 Data bits
Stop bit	1 Stop bit

6. SYSTEM RESET

Power on the meter, use the two fingers to press " Set Button " (3-4, Fig. 1) and " ▼ Button " (3-5, Fig. 1) continuously more than 2 seconds until the Display show the text " rSt ", release the buttons. After " rSt " text flashing 3 times will return to the normal screen. The meter internal function will return the default value.

7. SENSITIVITY RELATIVE to the reference sensitivity at 80 Hz , according ISO 2954

Frequency		Normal	Relative sensitivity	
		value	Minimum	Maximum
			value	value
10	Hz	1.0	0.8	1.1
20	Hz	1.0	0.9	1.1
40	Hz	1.0	0.9	1.1
80	Hz	1.0	1.0	1.0
160	Hz	1.0	0.9	1.1
500	Hz	1.0	0.9	1.1
1000	Hz	1.0	0.8	1.1

Table 1

7. THE ADDRESS OF AFTER SERVICE CENTER

170516-PVB8219