

CONDUCTIVITY, TDS, SALT METER

Model : YK-22CTA



Your purchase of this CONDUCTIVITY, TDS, SALT METER marks a step forward for you into the field of precision measurement. Although this meter a complex and delicate instrument, its durable structure will allow many years of use if proper operating techniques are developed. Please read the following instructions carefully and always keep this manual within easy reach.

OPERATION MANUAL

TABLE OF CONTENTS

1. FEATURES.....	1
2. SPECIFICATIONS.....	2
2-1 General Specifications.....	2
2-2 Electrical Specifications.....	4
3. FRONT PANEL DESCRIPTION.....	6
4. FUNCTION SELECTION.....	8
5. CONDUCTIVITY/TDS MEASURING and CALIBRATION PROCEDURE.....	9
6. SALT MEASURING and calibration PROCEDURE.....	13
7. OTHER FUNCTION.....	15
7-1 Data Hold.....	15
7-2 Record (Max./ Min. reading).....	15
7-3 LCD Backlight ON/OFF.....	15
8. ADVANCED SETTING.....	16
9. POWER SUPPLY from DC ADAPTER.....	19
10. BATTERY REPLACEMENT.....	19
11. SYSTEM RESET.....	19
12. RS232 PC SERIAL INTERFACE.....	20
13. OPTIONAL ACCESSORIES.....	21

1. FEATURES

- * One meter for multi purpose operation :
CD/TDS, Salt measurement.
- * Conductivity : 200 μ S/2 mS/20 mS/200 mS.
- * Salt : 0 to 12 % salt (% weight).
- * CD/TDS/Salt probe.
- * Conductivity measurement can select μ S/mS or TDS
- * Conductivity measurement can select Temp. Coefficient of measurement solution.
- * ATC for the conductivity measurement.
- * Separate probe, easy for operation of different measurement environment.
- * Wide applications: water conditioning, aquariums, beverage, fish hatcheries, food processing, photography, laboratory, paper industry, plating industry, quality control, school & college, water conditioning.
- * LCD with green light backlight, easy reading.
- * Can default auto power off or manual power off.
- * Data hold, record max. and min. reading.
- * Microcomputer circuit, high accuracy.
- * Power by DC 9V (006 P) battery or DC 9V adapter.
- * RS232/USB PC COMPUTER interface.

2. SPECIFICATIONS

2-1 General Specifications

Circuit	Custom one-chip of microprocessor LSI circuit.
Display	LCD size : 52 mm x 38 mm LCD with green backlight (ON/OFF).
Measurement Function	Conductivity/TDS(Total Dissolved Solids) Salt Temperature(°C, °F)
Advanced setting	<ul style="list-style-type: none">* Auto power OFF management* Set beep Sound ON/OFF* Set temperature unit to °C or °F* Set CD temperature compensation factor* Set CD to TDS or TDS to CD, CD only
Data Hold	Freeze the display reading.
Memory Recall	Maximum & Minimum value.

Sampling Time of Display	Approx. 1 second.
Data Output	RS 232/USB PC computer interface. * <i>Connect the optional RS232 cable UPCB-02 will get the RS232 plug.</i> * <i>Connect the optional USB cable USB-01 will get the USB plug.</i>
Operating Temperature	0 to 50 °C .
Operating Humidity	Less than 85% R.H.
Power Supply	Alkaline or heavy duty DC 9V (006 P) battery , or equivalent.
	DC 9V adapter input. (AC/DC power adapter is optional).
Power Current	Normal operation (LCD Backlight is OFF) : Approx. DC 14 mA.
	* <i>If LCD backlight on, the power consumption will increase approx. 12 mA.</i>
Weight	489 g/1.08 LB.
Dimension	195 x 68 x 30 mm (7.7 x 2.7x 1.2 inch)
Accessories Included	* Instruction manual..... 1 PC * Hard carrying case (CA-06)..... 1 PC * Conductivity/TDS probe, Salt probe, CDPB-03..... 1 PC
Optional Accessories	* 1.413 mS Conductivity Standard Solution..... CD-14 AC to DC 9V adapter. USB cable, USB-01. RS232 cable, UPCB-02. Data Acquisition software, SW-U801-WIN.

2-2 Electrical Specifications (23±5 °C)

A. Conductivity

Conductivity probe	Optional, Carbon rod electrode for long life.
Function	* Conductivity (uS, mS) * TDS (Total Dissolved Solids, PPM) * Temperature (°C, °F)
Temperature Compensation	Automatic from 0 to 60 °C (32 - 140 °F), with temperature compensation factor variable between 0 to 5.0% per C.
Probe Operating Temp.	0 to 60 °C .
Probe Dimension	Round, 22 mm Dia. x 120 mm length.
Optional probe and accessories	* Conductivity probe..... CDPB-03 * 1.413 mS Conductivity Standard Solution..... CD-14

1. Conductivity (uS, mS)

Range	Measurement	Resolution	Accuracy
200 uS	0 to 200.0 uS	0.1 uS	±(2% F.S.+1d) * F.S. - full scale
2 mS	0.2 to 2.000 mS	0.001 mS	
20 mS	2 to 20.00 mS	0.01 mS	
200 mS	20 to 200.0 mS	0.1 mS	
* Temperature Compensation : Automatic from 0 to 60 °C (32 - 140 °F), with temperature compensation factor variable between 0 to 5.0% per C. * The accuracy is specified under measurement value ≤ 100 mS. * mS - milli Simens			

2. TDS (Total Dissolved Solids)

Range	Measurement	Resolution	Accuracy
200 PPM	0 to 132 PPM	0.1 PPM	±(2% F.S.+1d) * F.S. - full scale
2,000 PPM	132 to 1,320 PPM	1 PPM	
20,000 PPM	1,320 to 13,200 PPM	10 PPM	
200,000 PPM	13,200 to 132,000 PPM	100 PPM	
* Temperature Compensation : Automatic from 0 to 60 °C (32 - 140 °F), with temperature compensation factor variable between 0 to 5.0% per °C. * The accuracy is specified under measurement value ≤ 66,000 PPM. * PPM - parts per million * @ 23±5 °C			

3. Temperature

Function	Measuring Range	Resolution	Accuracy
°C	0 °C to 60 °C	0.1 °C	±0.8 °C
°F	32 °F to 140 °F	0.1 °F	±1.5 °F
* @ 23±5 °C			

B. Salt

Conductivity probe	Optional, Carbon rod electrode for long life.
Measurement Range	0 to 12 % salt (% weight).
Resolution	0.01 % salt.
Accuracy	0.5 % salt value * F.S. : full scale.
Temperature Compensation	Automatic from 0 to 60 °C (32 - 140 °F), with temperature compensation factor variable between 0 to 5.0% per C.
Probe Operating Temperature	0 to 60 °C .
Probe Dimension	Round, 22 mm Dia. x 120 mm length.
Optional probe and acc	* Salt probe (Conductivity probe)..... CDPB-03

@ Above specification tests under the environment RF Field Strength less than 3 V/M & frequency less than 30 MHz only.

3. FRONT PANEL DESCRIPTION




Fig. 1

- 3-1 Display
- 3-2 Power Button (Backlight Button)
- 3-3 Hold Button (ESC Button)
- 3-4 REC Button
- 3-5 ▲ Button (Range Button)
- 3-6 ▼ Button (Function Button)
- 3-7 SET Button
- 3-8 Enter Button
- 3-9 Stand
- 3-10 Battery Compartment/Cover
- 3-11 Battery Cover Screw
- 3-12 Tripod Fix Nut
- 3-15 CD Socket
- 3-17 DC 9V Power Adapter Input Socket
- 3-18 Reset Button
- 3-19 RS-232 Output Terminal

4. FUNCTION SELECTION

- 1) Turn on the meter by pressing the " Power Button "
(3-2, Fig. 1) momentarily.

** Pressing the " Power Button " (3-2, Fig. 1)
continuously and > 2 seconds again will turn off the
meter.*

- 2) The meter can select 3 kind Function as :

- a. **Conductivity**
- b. **TDS measurement**
- c. **Salt measurement**

Pressing the " Function Button " (3-5, Fig. 1) once, the
Display will show the following text in sequence :

Cd	Conductivity, TDS measurement
TDS	TDS measurement
SALt	Salt measurement

Until the Display show the desired mode the meter will
execute this Mode with default.

5. CONDUCTIVITY/TDS MEASURING and CALIBRATION PROCEDURE

The meter default function are following :

- * The display unit is set to conductivity (μS , mS).
- * The temperature unit is set to $^{\circ}\text{C}$.
- * Temp. compensation factor is set to 2.0% per C.
- * Auto range.
- * Auto power off.




Fig.2



If the meter along with the conductivity probe are used for a certain period, then it should execute the calibration procedures, refer chapter 5-3, page 11.

5-1 Conductivity measurement

- 1) Prepare the Conductivity Probe (included, CDPB-03), install the " Probe Plug " (6-1, Fig. 2) into the " CD Socket " (3-15, Fig. 1).
- 2) Power on the meter by pressing " Power Button " (3-2, Fig. 1) once.
Select the Meter's measurement Function to " Cd " (Conductivity measurement), refer to chapter 4, page 8.
- 3) Hold the " Probe Handle " (6-2, Fig. 2) by hand and let the " Sensing head " (6-3, Fig. 2) immersed wholly into the measured solution. Shake the probe to let the probe's internal air bubble drift out from the sensing head.
Display will show the conductivity mS (μ S) values.
at the same time the left bottom display will show the Temp. value of the measured solution.

Manual range operation

The meter is default to be used for the auto range mode. Push the " Range Button " (3-6, Fig. 1) once in sequence will change the range from 200 μ S, 2 mS, 20 mS, 200 mS and auto range.

Change the Temp. unit to °F

If intend to change the Temp. unit from °C to °F, please refer to chapter 8-3 page 17.

Change the Temp. Coefficient Factor

The default Temp. compensation factor value of the measurement solution is to 2.0% per °C. If intend to change it, please refer to chapter 8-4, page 18.

Zero adjustment

If the probe not immerse the measurement solution and display not show zero value, pressing the " Zero (RANGE) Button " (3-5, Fig. 1) continuously at least 10 seconds will let display show zero. The zero function only valid for the 200 uS range and the not zero value is < 2.0 uS.

5-2 TDS (PPM) measurement

The measuring procedures are same as above

5-1 Conductivity (uS, mS) measurement,

Then Use Function Key select to TDS Function position.

5-3 Calibration

- 1) Prepare the standard conductivity solution (optional)

For example :

2 mS range calibration solution :

1.413 mS Conductivity Standard Solution, CD-14

200 uS range calibration solution :

80 uS Conductivity Standard Solution

20 mS range calibration solution :

12.88 mS Conductivity Standard Solution

or other Conductivity Standard Solution


- 2) Install the " Probe Plug " (6-1, Fig. 2) into the " CD Socket " (3-15, Fig. 1).
- 3) Power on the meter by pressing " Power Button " (3-2, Fig. 1) once.
Select the Meter's measurement Function to " Cd "
(Conductivity measurement)

- 4) Hold the " Probe Handle " (6-2, Fig. 2) by hand and let the " Sensing head " (6-3, Fig. 2) immersed wholly into the measured solution. Shake


the probe to let the probe's internal air bubble drift out from the sensing head.

Display will show the conductivity mS (uS) values.

- 5) Use the two fingers to press the " ▲ Button " (3-5, Fig 1) and " ▼ Button " (3-6, Fig. 1) at the same time. the display will show the following screen as example, release the both fingers.



- 6) Press the " Enter Button " (3-4, Fig. 1), the measuring value will present on both upper and lower Display. Use "▲ Button " (3-5, Fig. 1), " ▼ Button " (3-6, Fig. 1) to adjust the up display value exact same as the standard conductivity value. Press the " Enter Button " (3-4, Fig. 1) will save the calibration data and finish the calibration procedures.



- * ***If only intend to make the one point calibration, just execute the 2 mS range (1.413 mS Cal.) is enough.***
- * ***Multi-points calibration procedures should execute the 2 mS range (1.413 mS Cal.) calibration at first, then make other ranges (20 uS range, 20 mS range or 200 mS range) calibration procedures following if necessary.***

6. SALT MEASURING and CALIBRATION






Fig.3

6-1 Salt measurement

- 1) Prepare the Conductivity Probe (included, CDPB-03), install the " Probe Plug " (7-1, Fig. 3) into the " CD Socket " (3-15, Fig. 1).
- 2) Power on the meter by pressing " Power Button " (3-2, Fig. 1) once.
Select the Meter's measurement Mode to " SALT " (Conductivity measurement)
- 3) Hold the " Probe Handle " (7-2, Fig. 3) by hand and let the " Sensing head " (7-3, Fig. 3) immersed wholly into the measured solution. Shake the probe to let the probe's internal air bubble drift out from the sensing head.
Display will show the Salt values (% weight).

6-2 Calibration

If the conductivity range already make the calibration completely then the Salt measurement is not necessary to make the calibration again.

7. OTHER FUNCTION

7-1 Data Hold

During the measurement, press the " Hold Button " (3-3, Fig. 1) once will hold the measured value & the LCD will display a " HOLD " symbol.

Press the " Hold Button " once again will release the data hold function.

7-2 Data Record (Max., Min. reading)

- 1) The data record function records the maximum and minimum readings. Press the " REC Button " (3-4, Fig. 1) once to start the Data Record function and there will be a " REC. " symbol on the display.
- 2) With the " REC. " symbol on the display :
 - a) Press the " REC Button " (3-4, Fig. 1) once, the " REC. MAX. " symbol along with the maximum value will appear on the display.

If intend to delete the maximum value, just press the " Hold Button " (3-3, Fig. 1) once, then the display will show the " REC. " symbol only & execute the memory function continuously.

- b) Press the " REC Button " (3-4, Fig. 1) again, the " REC. MIN. " symbol along with the minimum value will appear on the display.

If intend to delete the minimum value, just press the " Hold Button " (3-3, Fig. 1) once, then the display will show the " REC. " symbol only & execute the memory function continuously.
 - c) To exit the memory record function, just press the " REC " button for 2 seconds at least. The display will revert to the current reading.

7-3 LCD Backlight ON/OFF

After power ON, the " LCD Backlight " will light automatically. During the measurement, press the " Backlight Button " (3-2, Fig. 1) once will turn OFF the " LCD Backlight ".

Press the " Backlight Button " once again will turn ON the " LCD Backlight " again.

8. ADVANCED SETTING

press the " SET Button " (3-7, Fig. 1) continuously at least two seconds will enter the " Advanced Setting " mode. then press the " SET Button " (3-7, Fig. 1) once a while in sequence to select the eight main function, the display will show :

- PoFF**..... Auto power OFF management
- bEEP**..... Set beeper sound ON/OFF
- t-CF**..... Select the Temp. unit to °C or °F
- PEr C**..... Set CD temperature compensation factor, CD only

ESC..... **Escape from the advanced setting**

Remark :

- a. *CD - Conductivity/TDS Mode*
- b. *During execute the " Advanced Setting " function, if press " ESC Button " (3-3, Fig. 1) will exit the " Advanced Setting " function, the LCD will return to normal screen.*

8-1 Auto power OFF management

When the lower display show " PoFF "

- 1) Use the " ▲ Button " (3-5, Fig. 1) or " ▼ Button " (3-6, Fig. 1) to select the upper value to " yES " or " no ".

yES - Auto Power Off management will enable.

no - Auto Power Off management will disable.

- 2) After select the upper text to " yES " or " no ", press the " Enter Button " (3-8, Fig. 1) will save the setting function with default.

16

8-2 Set beeper sound ON/OFF

When the lower display show " bEEP "

- 1) Use the " ▲ Button " (3-5, Fig. 1) or " ▼ Button " (3-6, Fig. 1) to select the upper value to " yES " or " no ".

yES - Meter's beep sound will be ON with default.

**no - Meter's beep sound will be OFF with default.
is power ON.**

- 2) After select the upper text to " yES " or " no ", press the " Enter Button " (3-8, Fig. 1) will save the setting function with default.

8-3 Select the Temp. unit to °C or °F

When the lower display show " t-CF "

- 1) Use the " ▲ Button " (3-5, Fig. 1) or " ▼ Button " (3-6, Fig. 1) to select the upper Display text to " C " or " F ".

C - Temperature unit is °C

F - Temperature unit is °F

- 2) After Display unit is selected to " C " or " F ", press the " Enter Button " (3-8, Fig. 1) will save the setting function with default.

8-4 Set CD temperature compensation factor

When the lower display show " PEr C "

- 1) This function only for the Conductivity (TDS) Function of adjusting the probe's Temp.compensation value in %/per °C unit. The default value is 2 %/ per °C .
- 2) Use the " ▲ Button " (3-5, Fig. 1) or " ▼ Button " (3-6, Fig. 1) to select the upper value to the desired Temp. compensation value (%/per °C), then press the " Enter Button " (3-8, Fig. 1) will save the setting value temporally.

8-5 ESC


When the display show " ESC "

When the Display show the text " ESC ", then press the " ESC Button " (3-3, Fig. 1) will finish the Advanced Setting procedures and return to the normal measuring screen.

Remark :

During execute the " Advanced Setting " function, if press " ESC Button " (3-3, Fig. 1) will exit the " Advanced Setting " function, the LCD will return to normal screen.

10. BATTERY REPLACEMENT

- 1) When the left corner of LCD display show " , it is necessary to replace the battery. However, in-spec. measurement may still be made for several hours after low battery indicator appears before the instrument become inaccurate.
- 2) Loose the screws of the " Battery Cover " (3-11, Fig. 1) and take away the " Battery Cover " from the instrument and remove the battery.
- 3) Replace with DC 9V (006 P battery Alkaline/heavy duty), and reinstate the cover.
- 4) Make sure the battery cover is secured after changing batteries.

11. SYSTEM RESET

If the meter happen the troubles such as :


CPU system is hold (for example, the key button can not be operated...).

Then make the system RESET will fix the problem.
The system RESET procedures will be either following method :

During the power on, use a pin to press the " Reset Button " (3-18, Fig. 1) once a while will reset the circuit system.

12. RS232 PC SERIAL INTERFACE

The instrument has RS232 PC serial interface via a 3.5 mm terminal (3-19, Fig. 1).
The data output is a 16 digit stream which can be utilized for user's specific application.
A RS232 lead with the following connection will be required to link the instrument with the PC serial port.



The 16 digits data stream will be displayed in the following format :

Each digit indicates the following status :

D15	Start Word		
D14	4		
D13	When send the upper display data = 1 When send the lower display data = 2		
D12, D11	Annunciator for Display		
	uS = 13	mS = 14	PPM = 19
	°C = 01	°F = 02	
D10	Polarity 0 = Positive 1 = Negative		

20

D9	Decimal Point(DP), position from right to the left 0 = No DP, 1= 1 DP, 2 = 2 DP, 3 = 3 DP
D8 to D1	Display reading, D1 = LSD, D8 = MSD For example : If the display reading is 1234, then D8 to D1 is : 00001234
D0	End Word

RS232 FORMAT : 9600, N, 8, 1

Baud rate	9600
Parity	No parity
Data bit no.	8 Data bits
Stop bit	1 Stop bit

13. OPTIONAL ACCESSORIES

RS232 cable UPCB-02	* Computer interface cable. * Used to connect the meter to the computer (COM port).
USB cable USB-01	* Computer interface cable. * Used to connect the meter to the computer (USB port).

Data	* The SW-U801-WIN is a multi
------	------------------------------

Acquisition software SW-U801-WIN	displays (1/2/4/6/8 displays) powerful application software, provides the functions of data logging system, text display, angular display, chart display, data recorder high/low limit, data query, text report, chart report.. .xxx.mdb data file can be retrieved for EXCEL, ACCESS.. wide intelligent applications.
-------------------------------------	---

Power adapter	AC 110V to DC 9V. USA plug.
Power adapter	AC 220V/230V to DC 9V. Germany plug.

Conductivity Salt optional accessories	* Conductivity/Salt probe Model : CDPB-03
	* 1.413 mS standard solution. Model : CD-14

